



Service Bulletin

File in Section: -

Bulletin No.: PIC5935

Date: November, 2013

PRELIMINARY INFORMATION

Subject: Revised Operation Of Hazard Switch

Models: 2014 Cadillac CTS Sedan

Condition/Concern

A customer may comment that the operation of their hazard switch does not activate during the first press.

Recommendation/Instructions

A BCM calibration has changed the operation of the Hazard Switch on the vehicles produced after 10/11/2013, or any vehicle that has had the BCM programmed during service. The Hazard Switch must be pressed and held for 1 second before the hazards will operate.

Customer Information

For vehicles built after 10/11/2013 or for vehicles built prior to 10/11/2013 in which the BCM has been reprogrammed, please communicate to the customer this condition is a normal operating characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.