



Service Bulletin

File in Section: -

Bulletin No.: PIC5896

Date: August, 2013

PRELIMINARY INFORMATION

Subject: Unable To Perform BCM Setup Or Config With GDS2 After Adding Accessories Or Programming The BCM

Models: 2013 - 2014 Chevrolet Spark

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A dealer technician may not be able to perform the BCM Setup or Config using GDS2 after adding options (i.e. Fog Lamps) and/or programming/updating the BCM software. The dealer may comment that there is a no comm message or it will not complete the procedure.

Recommendation/Instructions

If the concern above is exhibited in GDS2 only, the correction is to locate session history in GDS2 and delete the session history for this vehicle (VIN). When rebuilding the vehicle in GDS2, you MUST select with WHB.

ADDITIONAL SI KEYWORDS:

brake BPP BPPS C0277 calibrate calibration code DTC lights pedal position program sensor

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.