



File in Section: -

Bulletin No.: PIC5880B

Date: July, 2013

Service Bulletin

PRELIMINARY INFORMATION

Subject: SPARK EV (BEV) TAC Parts Restriction Program

Models: 2014 Chevrolet Spark EV (BEV)
Equipped with (RPO EVL, EN0)

This PI was superseded to update parts information. Please discard PIC5880A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement process, the following components will remain on restriction through the GM Technical Assistance Center (TAC).

Note: If the Drive Motor Battery or Drive unit is needed, refer to the latest versions of PIP5112 or PIP5131, respectively, to place the order.

Recommendation/Instructions

If diagnostics lead to the replacement of any of the components listed below, please contact TAC at Telephone Number US 877-446-8227 (Action Center prompt or Hybrid prompt) or Canada 800-263-7740 for English or 800-263-7960 for French.

Warranty Information

For vehicles repaired under warranty using parts listed, please use the corresponding labor op:

Component Code	Part Name	Part Number	Labor Op
A4	HV Drive Motor Battery (Complete Pack)	23176402	5030630
K114B	Hybrid Powertrain Control Module 2 (HPCM 2)	22985723	5410140
K118	Air Compressor Control Module (ACCM)	95270908	4417120
K17	Electronic Brake Control Module (EBCM)	23154359	2410370
K57	Onboard Charge Module (OBCM) Battery Charger Control Module	24267451	5040210
N/A	Drive Unit (Transaxle)	24257888	8464670
N/A	Brake Pressure Modulator Valve (BPMV)	20864952	2410170
S15	Manual Service Disconnect (MSD) Connector Drive Motor Battery High Voltage Manual Disconnect Lever	13583086	N/A
T1	Accessory Power Module (APM) Accessory AC and DC Power Control Module	24267785	5010220
T24	DC Fast Charger - High Content (HPCC) High Voltage Battery Disconnect Control Module	23164011	5010230
T24	AC Charger - Low Content (HPCC) High Voltage Battery Disconnect Control Module	22985451	5010230
T6	Hybrid Powertrain Control Module (HPCM) Drive Motor Generator Power Inverter Module (TPIM)	12652453	5010240

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.