



Service Bulletin

File in Section: -

Bulletin No.: PIC5877

Date: June, 2013

PRELIMINARY INFORMATION

Subject: OnStar System Setting Intermittent Red Fault Indicator And History DTC U1804

Models: 2013 Chevrolet Camaro
with Frameless Inside Rearview Mirror (RPO DBX)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer may report that a red fault indicator comes up on the mirror at times. When checking for codes, only DTC U1804 may be set as history in the VCIM.

Recommendation/Instructions

Engineering is currently researching the issue. Please call GM Technical Assistance (GM TAC) for further assistance.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.