



Service Bulletin

File in Section: -

Bulletin No.: PIC5846

Date: April, 2013

PRELIMINARY INFORMATION

Subject: Service Brake Assist Message With DTC C025E SYM5A

Models: 2013 Chevrolet Trax
2013 Buick Encore

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Service Brake Assist message may be displayed on the DIC. Upon dealer diagnosis they may find DTC C025E Symptom 5A.

Recommendation/Instructions

Important: Do NOT Replace any parts for this concern.

Remove and inspect the connector from the Auxiliary brake assist Vacuum pump motor and inspect the Terminals, if no concerns are found to fully seat the connector clear the DTC's and re-evaluate the concern.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.