

TECHNICAL BULLETIN
JTB00304NAS1
16 SEP 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-05

Sun Visor - Lower-Level Service Repair

AFFECTED VEHICLE RANGE:

XF (X250)

Model Year: 2009 Onwards
VIN: R00019 Onwards

XJ Range (X351)

Model Year: 2010 Onwards
VIN: V00325 Onwards

XK Range (X150)

Model Year: 2007 Onwards
VIN: B00379 Onwards

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A lower-level service repair part is now available in the event of a front sun visor vanity mirror issue.

Cause: A lower-level service repair part to be used in the event a front sun visor vanity mirror requires replacement.

Action: Should a customer express this concern, follow the Service Instruction outlined below.

PARTS:

C2Z27679XXX Kit Sun visor Vanity (NAS) Quantity: 1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIX to obtain the latest repair time.**



 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Illuminated sun visor mirror assembly renew	76.10.50	0.2	01	C2Z2417

 **NOTE: Normal Warranty policies and procedures apply.**

SERVICE INSTRUCTION:

1. Using a suitable tool, release the retaining clips and remove the sun visor vanity mirror from the sun visor.



E150926

2.  **CAUTION: Do not use excessive force to install the new sun visor vanity mirror.**

Install new sun visor vanity mirror, pressing firmly against the areas indicated until an audible 'click' is heard.



E150927