



Service Bulletin

File in Section: -

Bulletin No.: PIC5838

Date: April, 2013

PRELIMINARY INFORMATION

Subject: TAC Part Restriction - Power Window Master Switch and Circuit Board

Models: 2009 Pontiac Vibe

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement efforts, the following Power Window Master Switch-related part numbers are currently restricted through the Technical Assistance Center (TAC):

19204262 - Power Window Master Switch

19205538 - Power Window Master Switch Circuit Board

Recommendation/Instructions

Before considering Power Window switch replacement, please review the latest version of Safety Recall 12071, document all of your results, and repair as necessary. If the concern is still present or if the diagnosis leads to replacement of either the circuit board or (in some cases) the power window switch, contact TAC (Technical Assistance Center) to review your test results.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.