

18.12.2012

16:26:08

52 km

2

255

Technical Service Bulletin

37 Transmission warning message in cluster (DTC P060A00)

37 13 78 2031675/1 January 8, 2013.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment | |
|----------|------|-----------|----------------------------|--|
| A8 | 2013 | All | O Cread transmission ODK | |
| S8 | | | 8 Speed transmission 0BK | |

Condition

Customer Complaint:

Transmission warning message in cluster.

Workshop Findings:

- DTC P060A00 (Control module internal processor monitoring) stored in the TCM.
- No other concerns noted with vehicle.

Technical Background

The entry **P060A00** with **DFCC 12480** can be logged in the TCM. This fault is only a diagnostic error. The fault will not affect vehicle performance.

12480 P060A00 [32] The DFCC is the Control module internal processor monitoring 4-6 digit code that Sporadic is typically listed Ambient requirements: before the fault Standard values: (Figure 1). Date Time km-Mileage Param DTCPrior Occurence Counter Central-Aging-Counter

Figure 1. 4-6 digit DFCC code



Technical Service Bulletin

Production Solution

Not applicable.

Service

If the above DTC is stored in the TCM along with the DFCC according to this TSB, delete the above entry of the gearbox control unit and explain to the customer the technical background.

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Instruct the customer that this condition is known, and a solution is under development.

If different DFCCs are present, this TSB does not apply.

Audi

Technical Service Bulletin

Warranty

| Claim Type: | Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only. | | | | |
|------------------|----------------------------------------------------------------------------------------------------------------------------|--------------|------------------------------------------------|--|--|
| Service Number: | 3730 | | | | |
| Damage Code: | 0039 | | | | |
| Diagnostic Time: | GFF includes checking and clearing fault. | 0150 0000 | Time stated on diagnostic protocol (Max 40 TU) | | |
| | Road test prior to service procedure | No allowance | 0 TU | | |
| | Road test after service procedure | No allowance | 0 TU | | |
| | Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details) | | | | |
| Claim Comment: | As per TSB #2031675/1 | | | | |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.