

48 Steering wheel leather damage, all vehicles

48 13 54 2028220/3 September 13, 2013. Supersedes Technical Service Bulletin Group 48 number 12-30 dated June 25, 2012 for reasons listed below.

Model(s	s) Year	VIN Range	Vehicle-Specific Equipment
All	2005 - 2014	All	Not Applicable

Condition

REVISION HISTORY				
Revision	Date	Purpose		
3	-	Revised header data (Added model year) Revised <i>Technical Background</i> (Clarified description)		
2	6/25/2012	Revised header data (Added model year 2013) Revised title		
1	12/7/2011	Original publication		

Steering wheel appearance damaged due to external impact (e.g., contact with finger nails, zippers, watches, rings, etc.).

Technical Background

© 2013 Audi of America, Inc.

External impact (e.g., contact with finger nails, zippers, watches, rings etc.) can cause damage to the appearance of the steering wheel (Figure 1 and Figure 2). This type of damage is not warrantable, as numerous investigations have shown that there is no fault in material or workmanship.



Figure 1. Example of damage from external impact.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin



Figure 2. Example of damage from external impact.

Production Solution

Not applicable.

Service

Not applicable.

Warranty

This damage is due to outside influence and is not covered by any Audi warranty.

Additional Information

All parts and service references provided in this TSB (2028220) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2013 Audi of America, Inc.

Page 2 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.