	2011-13MY Forester Turbo w/ AT 2011 and 2012MY Impreza 2.0 and 2.5L N/A w/ MT
SUBJECT:	ECM Reprogramming Availability for DTC P050A
INTRODUCTION	

TRANS.

TYPE

IMPORTANT - All

Service Personnel

Should Read and

Initial in the boxes provided, right.

This Bulletin announces the availability of ECM reprogramming files to address a false CEL/MIL illumination and setting of DTC P050A. This DTC can result from specific clutch operation (on MT models) and / or driving patterns occurring immediately after starting the engine.

**NEW ECM PART** 

NUMBER

SERVICE BULLETIN

2011 and 2012MY Legacy N/A and Turbo w/ MT

2011 and 2012MY Forester N/A w/ MT

PAK FILE NAME

# PACK FILE APPLICABILITY

EMISSION

SPEC.

ATTENTION:

GENERAL MANAGER

CLAIMS PERSONNEL

**APPLICABILITY:** 

**MODEL YEAR** 

/ MODEL

PARTS MANAGER

SERVICE MANAGER

CAL		0070540005			
2011 CAL		22765AC92E.pak	22765AC92E	22765AC92A, B, C, D	EE5IB50U
FED/CAL		22765AC94E.pak	22765AC94E	22765AC94A, B, C, D	EE5IB50W
Turbo		22765AC96D.pak	22765AC96D	22765AC96A, B, C	AE5IB50E
CAL		22765AC65E.pak	22765AC65E	22765AC65A, B, C, D	EE5K900U
FED/CAL		22765AD31D.pak	22765AD31D	22765AD31A, B, C	EE5K900W
Outback Turbo		22765AD30C.pak	22765AD30C	22765AD30A, B	AE5K900E
FED	MT	22765AD003.pak	22765AD003	22765AD000, 001, 002	EE5IB50G
2012 Impreza FED		22765AC405.pak	22765AC405	22765AC400, 401, 402, 403, 404	EP5G900A
		22765AC365.pak	22765AC365	22765AC360, 361, 362, 363, 364	EP5G900C
CAL 2011 FED Forester	22765AB418.pak	22765AB418	22765AB410, 411, 412, 413, 414, 415, 416, 417	EP5DA00A	
		22765AB438.pak	22765AB438	22765AB430, 431, 432, 433, 434, 435, 436, 437	EP5DA00C
Turbo	4AT	22765AB285.pak	22765AB285	22765AB280, 281, 282, 283, 284	AE5IB41R
	FED/CAL Turbo CAL FED/CAL Turbo FED CAL FED CAL FED	FED/CALTurboCALFED/CALTurboFEDALFEDCALFEDCALFEDFEDCAL	FED/CAL 22765AC94E.pak   Turbo 22765AC96D.pak   CAL 22765AC65E.pak   FED/CAL 22765AD31D.pak   Turbo 22765AD30C.pak   FED 22765AD30C.pak   FED 22765AD30C.pak   CAL 22765AD30C.pak   FED 22765AC405.pak   CAL 22765AC365.pak   FED 22765AB418.pak   FED 22765AB438.pak	FED/CAL 22765AC94E.pak 22765AC94E   Turbo 22765AC96D.pak 22765AC96D   CAL 22765AC65E.pak 22765AC65E   FED/CAL 22765AD31D.pak 22765AD31D   Turbo 22765AD30C.pak 22765AD30C   FED 22765AD30C.pak 22765AD30C   FED 22765AD003.pak 22765AD003   CAL 22765AC405.pak 22765AC405   FED 22765AC365.pak 22765AC365   FED 22765AB418.pak 22765AB418   FED 22765AB438.pak 22765AB438	FED/CAL 22765AC94E.pak 22765AC94E 22765AC94A, B, C, D   Turbo 22765AC96D.pak 22765AC96D 22765AC96A, B, C   CAL 22765AC96D.pak 22765AC96D 22765AC96A, B, C   FED/CAL 22765AD31D.pak 22765AD31D 22765AD31A, B, C   Turbo 22765AD30C.pak 22765AD30C 22765AD31A, B, C   FED 22765AD30C.pak 22765AD30C 22765AD30A, B   FED 22765AC405.pak 22765AC405 22765AD000, 001, 002   CAL 22765AC405.pak 22765AC405 22765AC400, 401, 402, 403, 404   FED 22765AC365.pak 22765AC365 22765AC360, 361, 362, 363, 364   CAL 22765AB418.pak 22765AB418 22765AB410, 411, 412, 413, 414, 415, 416, 417   FED 22765AB438.pak 22765AB438 22765AB430, 431, 432, 433, 434, 435, 436, 437   FED 22765AB438.pak 22765AB285 22765AB280, 281, 282,

# Continued...

#### CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

#### SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



QUALITY DRIVEN® SERVICE

**OLD ECM PART NUMBER** 

NUMBER: 11-135-13

**DATE: 11/27/13** 

**NEW CID** 

NUMBER

MODEL YEAR / MODEL	EMISSION SPEC.	TRANS. Type	PAK FILE NAME	NEW ECM PART NUMBER	OLD ECM PART NUMBER	NEW CID NUMBER
2012 Forester FED Turbo	CAL	MT	22765AD405.pak	22765AD405	22765AD400, 401, 402, 403, 404	EP5G900a
	FED		22765AD424.pak	22765AD424	22765AD420, 421, 422, 423	EP5G900c
	Turbo	4AT	22765AD443.pak	22765AD443	22765AD440, 441, 442	AE5K801R
2013 Forester	Turbo	4AT	22765AE561.pak	22765AE561	22765AE560	AE5L501R

## **SERVICE PROCEDURE / INFORMATION**

- In the event of an ECM replacement, always confirm the new ECM has the most recent software and CID number installed before releasing the vehicle.
- **REMEMBER:** CID numbers are CASE-SENSITIVE.

## WARRANTY / CLAIM INFORMATION

For vehicles within the Federal Emissions Extended Defect Warranty period, this repair may be claimed using the following information:

LABOR DESCRIPTION	LABOR	FAIL	LABOR
	OPERATION #	CODE	TIME
MFI OBDII ECM Reprogramming	A455-288	UPG-48	0.4