

Technical Service Bulletin

90 Seat belt reminder light stays on

90 13 43 2035937/1 December 3, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7	2012	All	Not Applicable

Condition

- The seatbelt warning light is illuminated, but the passenger seatbelt is buckled.
- The seatbelt warning chime is not on.
- This bulletin only applies to 2012 vehicles equipped with navigation system.

Technical Background

Software of the instrument cluster control module needs to be updated.

Production Solution

New software in the instrument cluster control module, J285 (address word 17), addresses the condition.

Service

SVM Update Instructions

- 1. Follow all instructions in the attached TSB, 2011732: Software Version Management (SVM), operating instructions.
- 2. Update the Instrument Cluster Control Module (J285) using the SVM action code as listed in the table below if necessary.

Model	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Action Code
A6,A7	N/A	N/A	N/A	0377	17A012



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	9025				
Damage Code:	0039				
Labor Operations:	Charge Battery	2706 8950	10 TU		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 60TU)		
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2035937/1				

Additional Information

The following Technical Service Bulletin will be necessary to complete this procedure:

• TSB 2011732: Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2035937) are subject to change and/or removal. Always check with your Parts Dept. and service manuals for the latest information.