

96 Homelink controls pressed into roof assembly

96 13 66 2033802/2 June 27, 2013. Supersedes Technical Service Bulletin Group 96 number 13-57 dated May 2, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6/A7	2012-2014	All	Homelink

Condition

REVISION HISTO	EVISION HISTORY					
Revision Date Purpose		Purpose				
2	-	Revised Service (Updated VIN Break)				
1	5/2/2013	Initial publication				

Customer states the Homelink controls are pressed into the interior light assembly (Figure 1).



Figure 1. Homelink buttons pressed into the interior light assembly.

© 2013 Audi of America, Inc.

Page 1 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Technical Background

Clips holding the Homelink buttons in place are too weak.

Production Solution

Revised clips.

Service

- For vehicles built before VIN DN148000, replace only the interior light assembly.
- For vehicles built after VIN DN148000, replace both the interior light assembly and the Homelink controls. Retain all parts from the repair, as they will be requested by the Warranty Parts Return Center.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.					
Service Number:	9620					
Damage Code:	0010					
Labor Operations:	Replace interior light assembly	9620 5500	40 TU			
	Replace Homelink controls (if necessary)	9678 1950	10 TU			
Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations	No allowance	0 TU			
	Road test prior to service procedure	No allowance	0 TU			
	Road test after service procedure	No allowance	0 TU			
	Technical diagnosis at dealer's discretion					
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)					
Claim Comment:	As per TSB #2033802/2					

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

^{© 2013} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Required Parts and Tools

Part Number	Part Description	Quantity	
See ETKA	Interior and Reading Light	1	
See ETKA	Operating unit for garage door opener	1 (if necessary)	

Additional Information

All parts and service references provided in this TSB (2033802) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2013 Audi of America, Inc.

Page 3 of 3

all rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.