



Service Bulletin

File in Section: 08 - Body and Accessories

Bulletin No.: 13-08-43-002

Date: December, 2013

WARRANTY ADMINISTRATION


Subject: Information on Windshield Multifunction Sensor Mount Bracket Cover Replacement

Models: 2014 Cadillac ATS, XTS

Condition/Concern

When technicians are replacing the windshield multifunction sensor mount bracket cover due to the tabs not retaining the cover firmly in place, they are submitting the wrong labor operation for the repair being done.

Recommendation/Instructions



2760577

Replace the windshield multifunction sensor mount bracket cover (1), in the illustration above, following the windshield multifunction sensor mount bracket cover replacement in SI and submit the labor operation listed in the warranty information below.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2071280	Windshield Multifunction Sensor Mount Bracket Cover Replacement	Use Published Labor Operation Time

