



Service Bulletin

File in Section: -

Bulletin No.: PI0888

Date: January, 2013

PRELIMINARY INFORMATION

Subject: Sunroof Seal Misshaped or Raised Up Along Front Edge of Sunroof Opening

Models: 2013 Cadillac ATS
Equipped with Sunroof (RPO CF5)

Condition/Concern



3258224

Some customers may comment that the front edge of the sunroof glass seal may be puckered, misshaped or raised up.

This condition may be caused by the glass sunroof panel being out of adjustment.

Recommendation/Instructions

To correct the condition, adjust the glass sunroof panel to the sunroof opening. Refer to Sunroof Window Height and Opening Fit Adjustment in SI.

It should not be necessary to replace the seal.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
B2720	Sunroof Window Height and Opening Fit Adjustment	Use Published Labor Operation Time