



# Service Bulletin

File in Section: -

Bulletin No.: PI0894

Date: January, 2013

## PRELIMINARY INFORMATION

**Subject:** No Remote Detected Message Displayed on DIC

**Models:** 2013 Cadillac SRX

**Attention:** This PI also applies to export vehicles.

### Condition/Concern

Some customers may comment on a "No Remote Detected" message displayed on the driver information center (DIC). When this message is displayed, the remote transmitter is inside the vehicle and the engine can be started or the ignition can be turned on.

### Recommendation/Instructions

An updated software calibration has been released to address this concern. Reprogram the body control module (BCM) using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the Body Control Module Programming and Setup procedure in SI.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
D4808	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time