File in Section:

Bulletin No.: Pl0908

Date: February, 2013

## PRELIMINARY INFORMATION

Subject: DIC Displays Cross Traffic Alert Off Message – Middle East Export Only

Models: 2013 GMC Terrain

**Equipped with RPO UFT** 

**Built Prior to VIN Breakpoint D6264599** 

**Condition/Concern** 

Some customers may comment on a Cross Traffic Alert Off and unable to reset.

This is caused by a software anomaly.

## Recommendation/Instructions

An updated software calibration has been released to address this condition.

Reprogram the side object sensing alert module using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

## **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
R9818*	Side Object Sensing Alert Module Reprogramming	0.4 hr
*This is a unique labor operation for bulletin use only. It will not be published in the Labor Time Guide.		