



# Service Bulletin

File in Section: -

Bulletin No.: PI0910

Date: February, 2013

## PRELIMINARY INFORMATION

**Subject:** Accessory Fog Lamp Inoperative

**Models:** 2013 Chevrolet Cruze  
Built Prior to November 30, 2012

### Condition/Concern

Some technicians may notice the accessory fog lamps are inoperative after installation.

This condition may be caused by the production body control module (BCM) not automatically enabling the fog lamp function.

### Recommendation/Instructions

The BCM software will need to be updated. Please contact the Techline Customer Support Center (TCSC) for instructions.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
N4808	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time