



Service Bulletin

File in Section: -

Bulletin No.: PI0912

Date: March, 2013

PRELIMINARY INFORMATION

Subject: Pre Delivery Inspection (PDI) - License Plate Packaged with Wrong Bolt

Models: 2013 Buick Encore
2013 Chevrolet Trax (Canada Only)
Built Prior to February 6, 2013

Condition/Concern

The front license package may contain incorrect bolts.



Note: Incorrect bolts have a round head as shown in the illustration above.

3285279



3285281

Note: Correct bolts have a hex-head as shown in the illustration above.

Recommendation/Instructions

Replace incorrect bolts with the following part number.

Parts Information

Part Number	Description	Qty
11588712	Bolt	2