



Service Bulletin

File in Section: -

Bulletin No.: PI0932

Date: March, 2013

PRELIMINARY INFORMATION

Subject: Flex Fuel Sensor and Bracket Part Change

Models: 2013 Chevrolet Impala

Due to a running change in production where 2012 flex fuel sensors and brackets were installed on some 2013 vehicles, the following service information is being provided.

Vehicles Built Prior to February 26, 2013

These vehicles were built with a 2013 flex fuel sensor and bracket. If a flex fuel sensor requires replacement, the bracket must also be replaced using the part numbers listed below.

Vehicles Built After February 26, 2013

These vehicles were built with a 2012 flex fuel sensor and bracket. If a flex fuel sensor requires replacement, the sensor only needs to be replaced with the part number listed below.

Parts Information

| Part Number | Description |
|-------------|--------------------|
| 13577379 | SENSOR, FLEX FUEL |
| 20862563 | BRACKET, FLEX FUEL |