



Service Bulletin

File in Section: -

Bulletin No.: PI0953

Date: April, 2013

PRELIMINARY INFORMATION

Subject: Unable to Make a Call Using Phone Icon on Radio

Models: 2013 Chevrolet Sonic
Equipped with Radio (RPO UH7)

Condition/Concern

Some customers may comment that calls cannot be made using the phone icon on the radio.
This may be caused by a software anomaly.

Recommendation/Instructions

An updated software calibration has been released to address this condition.
Reprogram the radio using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
R0759	Radio Reprogramming with SPS	Use Published Labor Operation Time