



Service Bulletin

File in Section: -

Bulletin No.: PI0953B

Date: June, 2013

PRELIMINARY INFORMATION

Subject: Unable to Make a Call Using Phone Icon on Radio

Models: 2013 Chevrolet Sonic, Spark, Trax
Equipped with Radio RPOs UH7, UMT or UM7

This PI is being revised to add the Trax model and radio RPOs UMT and UM7.
Please discard PI0953A.

Condition/Concern

Some customers may comment that calls cannot be made using the phone icon on the radio.
This may be caused by a software anomaly.

Recommendation/Instructions

An updated software calibration has been released to address this condition.
Reprogram the radio using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time