



Service Bulletin

File in Section: -

Bulletin No.: PI0975

Date: May, 2013

PRELIMINARY INFORMATION

Subject: DTC B125A.01 Set

Models: 2014 Chevrolet Impala LS
Equipped with Base Radio (RPO IO3)

Condition/Concern

Some technicians may find DTC B125A.01 set as current or in history. This DTC may be set falsely without an actual condition with the module.

This condition may be caused by a software anomaly.

Recommendation/Instructions

Clear the code. An updated software calibration will be released to address the false DTC in the near future. DO NOT replace the radio or the antenna amplifier for this condition.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4069929	Electrical Controls – Labor Only (To Clear DTC B125A.01)	0.2 hr