



Service Bulletin

File in Section: -

Bulletin No.: PI0988

Date: June, 2013

PRELIMINARY INFORMATION


Subject: Pop or Clunk Noise When Turning Steering Wheel at a Stop or Low Speeds

Models: 2010-2013 Chevrolet Impala

Condition/Concern

Some customers may comment on a clunk or pop type noise when turning the steering wheel at a stop or at low speeds.

Recommendation/Instructions



3423457

Install the strut spacer as shown above. Refer to Strut, Strut Component, or Spring Replacement in SI.

Parts Information

Part Number	Description
23119610	Strut Spacer

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8033790	Strut, Strut Component, or Spring Replacement	Use Published Labor Operation Time
8033791	Strut, Strut Component, or Spring Replacement – Both Sides	Use Published Labor Operation Time