



SERVICE BULLETIN

Notification of UPS1813-1b: Right-Hand Tail Lamp – Loss of Directional Indicator Operation

26-APR-13

No.: SGI13-10

Section: **GENERAL
INFORMATION**

Market: **CAN / USA**

DESCRIPTION

A potential concern has been identified on a limited number of 2013 model year Land Rover Range Rover vehicles where the directional indicator in the right-hand tail lamp may stop functioning, with the associated warnings of failure through the double-speed 'tick-tock' noise and tell-tale flash. Normal directional indicator functionality will return following an ignition cycle.

AFFECTED VEHICLES / OWNER NOTIFICATION

The VIN range of affected vehicles is DA118581-DA122072.

ACTION TO BE TAKEN

Retailers are required to check DDW and **HOLD** all affected vehicles in the above VIN range that are in their control and refrain from releasing these vehicles for new or used vehicle sale pending further notice.

We are currently in the process of verifying the concern and anticipate that revised software will be available on or before 2 May 2013. A further communication will be sent to retailers when details become available.

Thank you for your cooperation in this matter. Jaguar Land Rover apologizes for any inconvenience this may cause.