



UPS1813: Right-Hand Tail Lamp – Loss of Directional Indicator Operation - Update

SERVICE
BULLETIN

08-MAY-13

No.: SGI13-11
(issue 2)

Section: GENERAL
INFORMATION

Market: CAN / USA

CHANGES ARE HIGHLIGHTED IN GRAY

△ **NOTE:** The VIN range of affected vehicles has changed from that issued on Service Bulletin SGI13-10. All vehicles within the VIN range DA118581-DA124160 may now be updated as per Technical Bulletin UPS1813-4bNAS2 using IDS-DVD134.02 v.134.

DESCRIPTION

A potential concern has been identified on a limited number of 2013 model year Land Rover Range Rover vehicles where the directional indicator in the right-hand tail lamp may stop functioning, with the associated warnings of failure through the double-speed 'tick-tock' noise and tell-tale flash. Normal directional indicator functionality will return following an ignition cycle.

AFFECTED VEHICLES

The VIN range of affected vehicles is DA118581-DA124160.

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by these programs prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles in the listed VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

△ **NOTE:** On completion of the Repair Procedure, customers may notice a change to the flashing of the rear directional indicators with a short pulse preceding each flash. This is normal.

For detailed repair instructions, refer to the Technical Bulletin UPS1813-2bNAS on TOPIx for complete repair details.

PARTS

No parts necessary

TOOLS

△ **NOTE:** The VIN range of affected vehicles has changed from that issued on Service Bulletin SGI13-10. All vehicles within the VIN range DA118581-DA124160 may now be updated as per Technical Bulletin UPS1813-4bNAS2 using IDS-DVD134.02 v.134.

IDS with latest IDS-DVD and Calibration File; first available on IDS-DVD134.02 v.134
Jaguar Land Rover-approved Midtronics Vehicle Power Supply

WARRANTY

△ **NOTE:** Check DDW to ensure that the vehicle is affected by these programs prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Always refer to the Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**Q309**' together with the relevant Option Code. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **02 November 2013** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY. / VALUE
Q309	B	Tune download - Central Junction Box (CJB)	86.90.09	0.20	-	-
Q309	C	Tune download - Central Junction Box (CJB)	86.90.09	0.20	-	-
		Drive in / drive out	02.02.02	0.20	-	-

Normal Warranty policies and procedures apply