



SERVICE BULLETIN

Notification of UPS3113-1b: Right-Hand C-Pillar Outer Panel Split on Leading Edge

04-JUN-13

No.: SGI13-12

Section: GENERAL
INFORMATION

Market: CAN / USA

DESCRIPTION

A potential concern has been identified on a limited number of 2013 model year Land Rover LR2 vehicles where the leading edge of the outer panel on the right-hand C-pillar on the corner into the door shut area may be split.

AFFECTED VEHICLES

The VIN range of affected vehicles is DH356255-DH360221.

ACTION TO BE TAKEN

Retailers are required to check DDW and **HOLD** all affected vehicles in the above VIN range that are in their control and refrain from releasing these vehicles for onward distribution, sale, or use pending completion of the inspection procedure detailed in Technical Bulletin UPS3113-1bNAS.

Thank you for your cooperation in this matter. Jaguar Land Rover apologizes for any inconvenience this may cause.

UPS3113-1b – AFFECTED VIN LIST

VIN	RETAILER
DH357718	Land Rover Alexandria
DH357419	Land Rover Cherry Hill
DH357421	Land Rover Cherry Hill
DH357720	Land Rover Guilford
DH357423	Land Rover Hanover
DH357425	Land Rover Hanover
DH357710	Land Rover Hinsdale
DH358001	Land Rover Indianapolis
DH357725	Land Rover Milford
DH357426	Land Rover Paramus
DH357427	Land Rover Paramus
DH357428	Land Rover Paramus
DH357431	Land Rover Paramus
DH357432	Land Rover Paramus
DH357434	Land Rover Paramus
DH357435	Land Rover Paramus
DH357719	Land Rover Virginia Beach
DH358012	Plaza Land Rover St. Louis