

Reference SSM63177

Models LR4 / L319

Title Discovery 4 / LR4 Roof Opening Panel Diagnostic`s

Category Body

Last modified 13-Feb-2013 00:00:00

Symptom 102000 Window/Glass

Concern

Discovery 4 / LR4 customers may report that the Roof Opening panel fails to open

Action

Content Should a Discovery 4 / LR4 customer report this concern it is important that the pinpoint diagnostics are followed in Topix WSM 501-17. These have been significantly updated and a low level Service Repair also added. Note that from 12MY (Vin A625580) the 'Lifter Arms' have now been released for Service as a low level Service Repair - Part No. LR040809.