



# Service Bulletin

File in Section: -

Bulletin No.: PIC5770A

Date: June, 2013

## PRELIMINARY INFORMATION

**Subject:** Full Blower and/or Heat from Vents After Restart

**Models:** 2013 Chevrolet Malibu  
with Manual HVAC (RPO C67)

This PI was superseded to remove heated seat information and keywords. Please discard PIC5770.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer or technician may indicate that intermittently when vehicle is started there is high blower and/or full heat from vents unwanted. This concern may be present with blower and temperature knobs in any position.

### Recommendation/Instructions

Reprogram the Electronic Climate Control Module (ECC) using SPS select ECC Remote Heater and Air Condition Control Module - Programming and once completed perform ECC Remote Heater and Air Condition Control Module - Setup. Evaluate performance of both systems.

### Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description                                   | Labor Time |
|-----------------|---|------------|
| 2810015         | Electronic Climate Control Module Programming | 0.3 hr     |

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.