



Service Bulletin

File in Section: -

Bulletin No.: PIC5800

Date: January, 2013

PRELIMINARY INFORMATION

Subject: Heated Steering Wheel And / Or Steering Wheel Control Switches Inoperative

Models: 2013 Cadillac ATS

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The Steering Wheel Controls or, if equipped, Heated Steering Wheel (RPO UVD) may be inoperative.

Recommendation/Instructions

Inspect for loose or missing 7.5A or 2A fuse(s) in the IP Electrical Center fuse block. If found, verify proper fuse terminal tension and replace the fuse or fuse block terminal as necessary.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N1720	Fuse Replacement	Use Published Labor Operation Time
N6650	Terminal Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.