



# Service Bulletin

File in Section: -

Bulletin No.: PI1033

Date: August, 2013

## PRELIMINARY INFORMATION

**Subject:** Incorrect Information on Underhood Fuse Block Label

**Models:** 2014 Chevrolet Cruze  
Equipped with 2.0L Diesel Engine (RPO LUZ) and  
Built Prior to VIN 1G1P75SZ7E7143991

### Condition/Concern

The underhood fuse block label incorrectly indicates the soot sensor and the LTE fuse locations.

### Recommendation/Instructions

- For vehicles built prior to VIN 1G1P75SZ7E7143991, the soot sensor fuse location was moved from fuse 29 to fuse 8.
- For vehicles built between VINs 1G1P75SZ2E7100918 and 1G1P75SZ7E7143991, the LTE fuse location was moved from fuse 14 to fuse 11.