



Service Bulletin

File in Section: -

Bulletin No.: PI1044

Date: September, 2013

PRELIMINARY INFORMATION

Subject: Poor A/C Performance, DTC B3933

Models: 2013-2014 Chevrolet Sonic

Condition/Concern

Some customers may comment on poor air conditioning performance during extended drives.

When checking the vehicle for DTCs, B3933 may or may not be present.

Recommendation/Instructions

Perform the recommended diagnostic procedures for DTC B3933 in SI. If DTC B3933 is not set and normal SI diagnosis does not resolve the condition, replace the Evaporator Air Temperature (EAT) sensor. Refer to Evaporator Air Temperature Sensor Replacement (LHD) in SI.

Parts Information

Part Number	Description	Quantity
95018085	SENSOR, A/C EVAPORATOR TEMP	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4430930	Evaporator Air Temperature Sensor Replacement	Use Published Labor Operation Time