



Service Bulletin

File in Section: -

Bulletin No.: PI1045

Date: September, 2013

PRELIMINARY INFORMATION

Subject: Locking Fuel Door Will Not Open or Difficult to Open

Models: 2013 Cadillac ATS
Equipped with Advanced Theft (RPO Y61)
Built Prior to May 5, 2013

Condition/Concern

Some customers may comment that the locking fuel door will not open or is difficult to open. This condition may be caused by a software anomaly.

Recommendation/Instructions

An updated software calibration has been released to address this concern. Reprogram the body control module (BCM) using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the Body Control Module Programming and Setup procedure in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time