



Service Bulletin

File in Section: -

Bulletin No.: PI1124

Date: December, 2013

PRELIMINARY INFORMATION

Subject: 110V Power Outlet Intermittently Inoperative


Models: 2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500

Condition/Concern

Some customers may comment on an inoperative 110V outlet when using certain devices.

The inverter shuts down the AC output for continuous power consumption from loads on the AC exceeding the values below:

1. AC output load is greater than 500 watts for 0.1 seconds
2. AC output load is greater than 300 watts for 2 seconds
3. AC output load is greater than 150 watts for 10 seconds



3655833

Recommendation/Instructions

Verify that any devices plugged into the 110V AC outlet is within the specified wattage specification.