



Service Bulletin

File in Section: -

Bulletin No.: PI1132

Date: December, 2013

PRELIMINARY INFORMATION

Subject: Service Driver Assist Message on DIC After Replacing Memory Seat Module

Models: 2013 Cadillac ATS
Equipped With Memory Seats (RPO A45) and Without UGN and UVZ

Condition/Concern

Some customers may comment on a Service Driver Assist message on the DIC after memory seat module replacement. This may be caused by the module calibration not being optimal for non-haptic seats.

Recommendation/Instructions

An updated software calibration has been released to address this condition.

Update the memory seat module using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the SPS procedures in SI.

Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description | Labor Time |
|-----------------|--|------------------------------------|
| 2810875 | Driver or Passenger Seat Adjuster Memory Module Reprogramming with SPS | Use Published Labor Operation Time |