



# Service Bulletin

File in Section: -

Bulletin No.: PIC5611A

Date: January, 2013

## PRELIMINARY INFORMATION

**Subject:** No Rear Camera Guideline Selection

**Models:** 2012-2013 Buick LaCrosse  
2012-2013 Chevrolet Equinox  
2012-2013 GMC Terrain  
2013 Chevrolet Malibu  
with Navigation Radio (RPO UYS or UEW)

**This PI was superseded to update models, model years and RPOs. Please discard PIC5611.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

No Rear Camera Guideline Selection

### Recommendation/Instructions

The owner's manual does not specify that the rear camera Guideline selection is only available on vehicles equipped with RPO UYS or UEW Navigation Radio. Please verify the vehicle has RPO UYS or UEW prior to performing any repairs. If equipped with UYS or UEW verify the Guideline option is turned on. This can be checked by pressing Config, Display, and then select Guidelines.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N9999	Electrical Controls - Labor Only	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.