



Service Bulletin

File in Section: -

Bulletin No.: PIC5696A

Date: April, 2013

PRELIMINARY INFORMATION

Subject: PQC Part Restriction - E39A ECM Has Ended

Models: 2013 Buick LaCrosse (LUK, LFW, LFX) 2.4L, 3.0L, 3.6L
2013 Buick Enclave (LLT) 3.6L
2013 Cadillac XTS (LFX) 3.6L
2013 Cadillac ATS (LFX, LCV, LTG) 3.6L, 2.5L, 2.0L
2013 Chevrolet Camaro (LFX) 3.6L
2013 Chevrolet Malibu (LCV, LTG) 2.5L, 2.0L
2013 Chevrolet Traverse (LLT) 3.6L
2013 GMC Acadia (LLT) 3.6L
Restricted PN: 12653998

Attention: Note: This P/N only applies to the Model Year 2013 (Does not fit 2012 and older)

This PI was superseded to end restriction. Please discard PIP5696.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

As part of our ongoing quality improvement efforts, the Electronic Control Module (ECM) was placed on restriction through the PQC (Product Quality Center). The PQC ECM restriction has now ended.

Recommendation/Instructions

General Motors Engineering would like to thank the dealers that participated in the ECM restriction. Dealers can now order the ECM through their parts department. Calls to the PQC are no longer necessary to order the ECM.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.