

Reference	SSM66697
Models	XF / X250 XJ / X351 XK / X150
Title	Title: 5.0L V8 (AJ133) overheating due to incorrect coolant fill
Category	Engine
Last modified	26-Jun-2013 00:00:00
Symptom	Cooling System Concerns
Content	<p><b>Issue:</b> After the engine coolant on a 5.0L V8 AJ133 engine has been partially or fully drained and filled, the customer experiences the engine overheating.</p> <p><b>Cause:</b> The refill procedure has not been completed correctly, resulting in insufficient coolant in the engine.</p> <p><b>Action:</b> When refilling the coolant system on AJ133 V8, make sure the TOPIx procedures are carefully followed. Please refer to the information below for the TOPIx sections:</p> <p>XK (X150) 303-03C XF (X250) 303-03D XJ (X351) 303-03b</p>