

Reference	SSM66717
Models	F-TYPE / X152
Title	F-Type Suspension Knock / Creak from rear of Vehicle
Category	Chassis
Last modified	27-Jun-2013 00:00:00
Symptom	304000 Suspension System
Content	<p><u>Issue:</u> A Customer may report a Knock or Creak from the rear of the vehicle when going over bumps or maneuvering at slow speed.</p> <p><u>Cause:</u> Absence of an isolator sleeve fitted to the rear Coil Spring.</p> <p><u>Action:</u> A Technical Service Bulletin is currently being compiled and will be published shortly, please do not attempt any short term repair methods such as lubrication and non-approved parts.</p> <p>The TSB will detail how to fit an isolator sleeve to each individual rear Coil Spring to eradicate the noise.</p>