



Mack Trucks, Inc.
Greensboro, NC USA

Service Program Trucks

This document replaces Service Program "ABS ECU Reprogramming"
PV729-PI0814 (USA 57447) dated 02.2013

Date	Group	No.	Release	Page
2.13	593	011	02	1(2)

ABS ECU Reprogramming CXU

PI0814, ABS ECU Reprogramming

(February 2013)

On certain MACK CXU Trucks built between 08/20/12 and 11/02/12, the software in the Bendix ABS module contains an incorrect setting.
To correct this issue follow the procedure below:

Required Parts


Part Number	Description
22084154	Reconfiguration RDU (Bendix Part Number K093037)

Procedure

1. To order part and instructions please call 1-866-865-1052.
2. Once programming is complete you **MUST** call 1-866-865-1052 to receive a return shipping label.

Note: Part **MUST** be returned in the same packaging as received.

Note: To signify that the campaign has been completed, using a permanent-type marker (such as a Sharpie®) write the campaign number (PI0814) and completion date in the spaces provided on the Campaign Completion label located inside the cab as shown in the illustration below. If a label is not already affixed inside the cab, apply a label (part No. TS897) and supply the information as required. Campaign Completion labels are available in packs of 50 and can be ordered by faxing a completed BR313 to Pacesetters Business Services at 610-264- 9465.



W8034103

Reimbursement

This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.	
Claim Type (used only when uploading from the Dealer Bus. Sys.)	B
Recall Status	
Vehicle inspected, repair not required	1- Inspected OK
Vehicle repaired per instruction	2- Modified per instruction
Labor Code	
Primary Labor Code (includes inspection and take charge)	7353B-ZP-96 0.3 hrs
Causal Part	21865546
Authorization Number	PI0814
Expiration Date	12-February-2014