

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013 BRZ
 2014 Forester
 2008-2013 Impreza
 2012-2014 Legacy/Outback

SUBJECT: Service Manual Corrections

NUMBER: 18-173-13
DATE: 08/19/13

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2014	Legacy/Outback	Body	ET-3,6,7,59-63	Changes to Audio System Diagnosis.
2013	Legacy/Outback	Body	ET-3,6,7,59-63	Changes to Audio System Diagnosis.
			SL-11,13-31	Door Lock Control Inspection and Symptom Chart changed.
2012	Legacy/Outback	Body	ET-3,6,7,56,57	Changes to Audio System Diagnosis.
2013	Impreza	Chassis	VDC(diag)-66	Diagnostic steps changed for DTC C1531.
			BR-73-75	Stop Light Switch installation instructions changed.
		Body	EI-8,56,57	Side Garnish illustration changes and installation steps and cautions changed.
2012	Impreza	Chassis	VDC(diag)-65	Diagnostic steps changed for DTC C1531.
			BR-70-72	Stop Light Switch installation instructions changed.
2011	Impreza	Chassis	VDC(diag)-75	Diagnostic steps changed for DTC C0054.
			BR-42-45	Brake Pedal removal and installation steps changed.
2010	Impreza	Chassis	VDC(diag)-73	Diagnostic steps changed for DTC C0054.
			BR-42-45	Brake Pedal removal and installation steps changed.
2009	Impreza	Chassis	VDC(diag)-73	Diagnostic steps changed for DTC C0054.
			BR-42-45	Brake Pedal removal and installation steps changed.

Continued...

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2008	Impreza	Chassis	VDC(diag)-72	Diagnostic steps changed for DTC C0054.
			BR-43-46	Brake Pedal removal and installation steps changed.
2014	Forester	Engine 1	EN(H4DO)(diag)-36,48,56,57	Drive Cycle changes.
			EN(H4DO)(diag)-96-99	Diagnostic steps changed for DTC P0016, P0018.
			LU(H4DO)-69,78,87,93	Oil Level Switch replacement, Drain & Refill Oil steps added.
		Engine 2	EN(H4DOTC)(diag)-37,49,50,58,59	Drive Cycle changes.
			EN(H4DOTC)(diag)-99-106	Diagnostic steps changed for DTC P0016, P0017, P0018, P0019.
			EN(H4DOTC)(diag)-177-180, 298-300	Illustration and diagnostic step changes for DTCs P0172 & P062D.
		Chassis	VDC(diag)-68,70	Diagnostic steps changed for DTC C1531.
			BR-76-78	Stop Light Switch installation instructions changed.
2013	BRZ	Engine Control	VVT Initial Position Learning Value Display	Procedure added.
		Lighting Exterior	Stop Light Switch	Installation procedure changed.