

RIDE THE DUCKS INTERNATIONAL
Fleet Operations & Safety
2320 West Highway 76
Branson MO 65616

Bulletin No. SB-00-11-13
Release Date: 5/29/13
Effective Date: 5/29/13
Supersedes: N/A
Completion Date: 250 P/I
Applicable to: All Diesel Truck
Ducks
Total Pages: 1

SERVICE BULLETIN

REASON FOR RELEASE: To mitigate the risk associated with radiator fan bolts coming loose.

Urgency:

Modification should take place as part of the 250 hour Periodic Inspection or sooner.

General:

This modification consists of a drilling a single hole in the head of each bolt that secures the radiator fan (6 bolts total)

Visual Direction

Stainless Steel Lock Wire, attached in a two bolt sequence. Ensure wire is secured not allowing a counter clockwise rotation of the bolt.

Wire spec: .041 SS Safety Lock Wire



NOTE: All work must be performed by qualified personnel. Use only authorized components, specified or provided by Ride The Ducks. All applicable OSHA safety standards and safe industry practices must be observed. Observe all safety information contained in the manufacturers manuals. Make available this bulletin and all related technical information to personnel using the equipment.

[CONTACT US VIA EMAIL](#)

RTDI FLEET OPS HOTLINE: 417 266 7676

RTDI PARTS: 417 266 7626