

Special Service Message



NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 66017 - Door seal creak LTB00525

Models : LV - Evoque

Engineer Name : Corthine Mark

Last Modified : 04-06-2013 07:39:01

Category : Body

Symptom : 110000 Sealing

Content : **Issue:** When carrying out this TSB for seal creak it has been noted that some dealers are changing individual seals instead of a full car set

Cause: This is due to the creak only being evident from one seal and that part being replaced only

Action: When carrying out TSB LTB00525 the seals must be **ordered and changed as a car set**. If seals are to be changed due to any other reason than creaking please order the old level parts which can be changed individually as required. There is a very limited stock of the TSB parts and they must only be ordered for the creaking issue.