

11310487403.JPG

113date code.JPG

Reference	SSM51797
Models	Range Rover Sport / L320 LR4 / L319 Range Rover / L322
Title	Smart Key cover detaching from the Casing
Category	Electrical
Last modified	19-Sep-2013 00:00:00
Symptom	203000 Basic Electrical
Content	<p><u>Please note: Refer to technical bulletin LTB00563 which shows a low level repair if this issue is applicable. You should not replace the complete key.</u></p> <p><u>Issue</u> The outer cover on the remote key can detach from the casing. See attachment.</p> <p><u>Cause</u> The Root cause was found to be that anti rust oil residue remains on the supplier's tooling at the start of a production run.</p> <p><u>Action</u> The issue is resolved from 18th September 2012. Please note that the casing is now available as a separate part. Please see technical bulletin LTB00563 and supporting animation SSM 66357.</p> <p><u>Discovery 4/LR4, Range Rover Sport up to 12MY, Range Rover (L322) All</u> 120918 (year 2012, month September, day 18th), see attachment for location.</p> <p>Please only submit EPQR's for failures after this assured date, your continued support is appreciated.</p>





DATE CODE: 101009
LEAR P/N: 5E0B601A7
JLR P/N: AH22-15K601-BF

CMIIT: 2009DJ2121
TRC: TRC/LPD/2009/81
KCC: LER-5E0B6P127

30/01/2012

