

Reference	SSM68037
Models	Range Rover Sport / L320 LR4 / L319 Range Rover / L322
Title	Incorrect diagnosis of navigation system
Category	Electrical
Last modified	06-Sep-2013 00:00:00
Symptom	207000 Entertainment Systems
Content	<p>Note: This message is applicable to Range Rover 10MY 11MY and 12MY Discovery 4/LR4 10MY and 11MY Range Rover Sport 10MY and 11MY. However you should always refer to the diagnostic section for each system in the workshop manual before replacing any modules.</p> <p>Issue A large number of Navigation modules are being replaced and when test by the supplier are "no fault found".</p> <p>Action Please ensure that you refer to the workshop manual in Topix, section 415-Information and entertainment systems 415-00 Navigation system- diagnostic and testing.before replacing the module. If the unit is replaced please reference this ssm number.</p>