

Reference	SSM68117
Models	Range Rover (All New) / L405 Range Rover Sport / L494
Title	2014 Range Rover / Range Rover Sport Not Exiting Valet Mode
Category	Electrical
Last modified	17-Sep-2013 00:00:00
Symptom	207000 Entertainment Systems
Content	<p><b><u>Concern</u></b> A customer may experience an issue where the vehicle will not exit out of Valet mode when the correct PIN is entered via the Touch Screen.</p> <p><b><u>Cause</u></b> Engineering are currently investigating this issue.</p> <p><b><u>Action</u></b> If a customer experiences the concern, the Valet mode will require resetting using SDD from the Service Functions menu.</p> <p>Please advise the customer, Land Rover is aware of the concern and is developing a solution. It is advisable, at this time, to refrain from using Valet mode to prevent the customer from being locked out of their Infotainment System. A communication will be issued once a fix has been developed.</p>