

Reference	SSM68137
Models	Range Rover (All New) / L405 Range Rover Sport / L494
Title	2014 Range Rover / Range Rover Sport Global Close Inoperative
Category	Electrical
Last modified	11-Sep-2013 00:00:00
Symptom	205000 Electrical Accessories
Content	<p><b><u>Concern</u></b> A customer may complain that their Global Close feature is not working.</p> <p><b><u>Cause</u></b> An inadvertent change to the vehicle has occurred which has disabled the feature. Engineering are currently investigating the concern.</p> <p><b><u>Action</u></b> In the event of a customer concern their Global Close feature is not working, no further diagnostic action is necessary at this time. Engineering are working on a fix which will enable the Global Close feature to operate via the keyless locking sensor located on the exterior door handle as described in the Owner's Handbook. A fix communication will be issued shortly.</p>