<b>Фтоус</b>	TA Teo	ch Tip ⊺-TT-031	0-14		October 15, 2014
Intermittent Knock or Tapping Noise at HV Transaxle USA and / or DTC P030# on Cold Engine Start					
Service Category Engine/Hybr Applicability	id System		Hybrid/Battery Contro	ol System	
2010-2012 2	ZR-FXE	C. La Maria	A Station of the second	as marchallant	all case with a
Applicable	VEHICLES				
2010-2012			Prius		
CONDITION					
			d and / or Runs Roug P0300, P0301, P0302		
RECOMMEND	ATIONS				
case please from the cus -Time the ev -How long th	attach any relevant F tomer: ent occurred (morning e car sat before the e	reeze Frame Dat g, evening, etc.) event	all for further instructions. If available, please short trip, long trip, etc	include the follo	
LINK REFERE	ENCES				
This Tech Tip does not contain any link references					
Expires on (	01/15/2015	© 2014, Toyota Mot	or Sales, USA		Page 1 of 1