

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

Audi
Truth in Engineering 

Audi Elsa Newsletter

Edition 113: November 24, 2014

Content

- [Offboard Diagnostic Information System Service \(ODIS Service\) – Installation Version 2.2.2 DVDs](#)
- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



Offboard Diagnostic Information System Service (ODIS Service) – Installation Version 2.2.2 DVDs

We are pleased to announce the availability this week of ODIS Service **Installation Version 2.2.2 DVDs**.

This new installation version consolidates all application and brand updates released online up to the DVD pressing date.

Consolidation of the recent data results in fast initial **installations on brand new diagnostic devices**, and fast **reinstallations on existing devices** to resolve malfunctioning software. This precludes the need to further download a large volume of online updates via your dealership network after installation and enables the devices to be put into service sooner.

V2.2.2 - Important Notes:

- Installation/reinstallation is performed from 2 DVDs.
- While the contents installed with V2.2.2 are very recent, online updates released after the version DVDs were pressed must still be downloaded and installed (a much smaller volume).
- Brand new VAS 6150C diagnostic laptop and VAS 6160A diagnostic tablet shipments from today's date are scheduled to include the V2.2.2 DVDs.
- **V2.2.2 is NOT an update version! Please DO NOT order and use the V2.2.2 DVDs on existing devices that already have the latest online updates installed and are functioning normally.**

As a result of the above, **V2.2.2 DVDs are not automatically shipped to every dealer**. Order these DVDs **ONLY** if you wish to reinstall the software on an existing device to resolve malfunctioning software.

The 2-DVD set is scheduled to be available for ordering mid-week from:

www.audi.techliterature.com - order number: **010.5002.02.21**

Technical Bulletins

85 Lack of heating or air conditioning (2033596/4)		
Model(s)	Year	Vehicle Specific Equipment
A4, Q5	2009–2014	Not Applicable
A5	2008–2014	Not Applicable
A5 Cabriolet	2010–2014	Not Applicable

Condition: One or more of the following DTCs may be stored in the heating and air conditioning electronics control module (address word 08):

- DTC 01844 004
- DTC 01844 014
- DTC 01273 009
- DTC 01273 006

Production Solution:

- Improved fresh air blower control module, J126.
- Improved brush assembly has been implemented in production.

[Back to top](#)

Pending Service Solutions

No new Pending Service Solutions this week.

Campaigns

No new campaigns this week.

Updates

No new updates this week.

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

[Back to top](#)

© 2014 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.