




ROADSTER 2014 Ignition Switch Mechanical And Electrical Failures_000077572_TST61Y014S10_en

Rate This Article  (Average Rating: No Rating) | Version 2

Summary:

2014 Roadsters may have a problem with the ignition switch, this TST will illustrate the possible failures.

Type:

General

TST Detail:

Please refer to warranty campaign 2014-2 for ignition switch failures such as:

- Unable to turn key in ignition switch
- Unable to remove key from ignition switch

Other problems have been identified, such as:

- Unable to open seat
- Unable to open front cargo
- Position lights Intermittently turning off when moving the key in the ignition switch

BRP is working on a solution to address these problems and identify the potentially affected units. If a unit is affected by these other problems, replace the ignition switch (710 003 596) and process a regular claim.

Note that the Ignition switch assy comes with the following items:

- Ignition switch
- 2 keys
- 2 plastic sheaths
- 2 barrels (1 for the rear cargo on the RT and 1 for the trailer, if applicable)

Attachment:

First Published By: Dany Davey on 2014-03-20

Last Modified By: Dany Davey on 2014-03-31