

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

**SSM 71238 - Exhaust sound enhancement vacuum pump - correct routing**

**Models :** X152 - F-Type

**Engineer** Sheriff Kirk

**Name :**

**Last** 21-01-2014 10:38:31

**Modified :**

**Category :** Engine

**Symptom :** 403000 Exhaust System Concerns

**Content :** Issue: A Customer may report a noise in the cabin area, that may appear to be coming from the rear left hand side of the Vehicle

Cause: This may be due to the vacuum hose on the exhaust sound vacuum pump, being in contact with the Body.

Action: Refer to TOPIx, workshop manual section 16768, exhaust system 309-00B.

The attachment shows the correct location for the vacuum hose and the location for the fitment of an additional clip. Part number C2S17736 Clip.

**Please note,** this SSM is interim until a Technical Service Bulletin is published.

**File :** [SSM71238 Vac hose1.pdf](#)

